

Number	Output Sockets	Fuse Protection or Equipment	RCD Type A Residual Current I _n I _{Δn}	Entry Screw Size	Order No.
--------	----------------	------------------------------	--	------------------	-----------

4 sockets with earthing contact	—	—	25A/30mA/2p.	M 20	2018001
1 CEE 400V 16A 5p. and 4 sockets with earthing contact	—	—	—	M 20	2008101
1 CEE 400V 32A 5p. and 2 sockets with earthing contact	—	2 B-Autom. 1p.	—	M 20	2048301



4 sockets with earthing contact	— quick-release connector	—	—	M 20 1/2 inch thread	2008001
1 CEE 400V 16A 5p. and 3 sockets with earthing contact	— quick-release connector	—	—	M 20 1/2 inch thread	2008102



2 sockets with earthing contact	—	—	25A/30mA/2p	M 20	2018002
1 CEE 400V 16A 5p. and 2 sockets with earthing contact	—	—	—	M 20	2008103
1 CEE 400V 32A 5p. and 2 sockets with earthing contact	—	2 B-Autom. 1p.	—	M 20	2048302



1 screw sized M 25	main switch 40A 400V 3 ~	—	—	M 25	2008801
1 screw sized M 20	reverse switch 40A 400V 3 ~	—	—	M 25	2008802
1 screw sized M 20	emergency push button	—	—	M 25	2008804



– other models on request / subject to modification and errors –