



Solid Rubber Housing
Series
REMSCHIED

Number	Output Sockets	Fuse Protection or Equipment	RCD Type A Residual Current I _n	Entry	Screw Size	Order No.
--------	----------------	------------------------------	--	-------	------------	-----------

6 sockets with earthing contact	6 B-Autom. 1p.	40A/30mA/4p.	M 25	2758010
6 sockets with earthing contact	6 Neokit 1p.	40A/30mA/4p.	M 25	2738002
6 sockets with earthing contact	9 B-Autom. 1p.	—	M 25	2748001



1 CEE 400V 16A 5p. and 3 sockets with earthing contact	1 C-Autom. 3p. 3 B-Autom. 1p.	40A/30mA/4p.	M 25	2758144
1 CEE 400V 32A 5p. and 3 sockets with earthing contact	1 C-Autom. 3p. 3 B-Autom. 1p.	63A/30mA/4p.	M 32	2758350
1 CEE 400V 16A 5p. and 3 sockets with earthing contact	1 Neokit 3p. 3 Neokit 1p.	40A/30mA/4p.	M 25	2738115



1 CEE 400V 32A 5p. and 1 CEE 400V 16A 5p. and 3 sockets with earthing contact	— 1 C-Autom. 3p. 3 B-Autom. 1p.	40A/30mA/4p.	M 32	2758340
1 CEE 400V 32A 5p. and 1 CEE 400V 16A 5p. and 3 sockets with earthing contact	1 C-Autom. 3p. 1 C-Autom. 3p. 3 B-Autom. 1p.	—	M 32	2748302



1 CEE 400V 63A 5p. and 2 sockets with earthing contact	— 2 B-Autom. 1p.	63A/30mA/4p.	M 32	2758607
1 CEE 400V 63A 5p.	1 C-Autom. 3p.	63A/30mA/4p.	M 32	2758601
1 CEE 400V 63A 5p.	—	63A/30mA/4p.	M 32	2718601



– other models on request / subject to modification and errors –