


ELSPRO Welding Products


Earthing Clamps (brass with copper brackets):

Fig.	Welding Current	Order No.
ALFA 1	500 A	EKA01
ALFA 2	600 A	EKA02




Earthing Clamps (galvanized steel sheet with copper brackets):

Fig.	Welding Current	Order No.
BETA 1	200 A	EKB01
BETA 2	500 A	EKB02



Earthing Clamps (galvanized steel sheet with copper brackets):

Fig.	Welding Current	Order No.
GAMMA 1	150 A	EKG01
GAMMA 2	200 A	EKG02
GAMMA 3	400 A	EKG03



Pol-Welding Screw Clamps (cast steel with copper brackets):

Fig.	Welding Current	Order No.
DELTA 1	600 A	EKD01
DELTA 2	400 A	EKD02



Battery Clamps (fully insulated galvanized steel sheet with copper brackets):

Model	Welding Current	Order No.
black straight	600 A	BK01
red straight	600 A	BK02
black angled	600 A	BK01W
red angled	600 A	BK02W



* customized earthing clamps, pol-welding screw clamps,
and battery clamps according to customer specifications *
– other items on request / subject to modification and errors –