



Solid Rubber Housing

Series
HILDEN

Configuration Example

Suspension and Wall-mounted Distribution Boxes



Number	Output	Sockets	Fuse Protection or Equipment	RCD Type A I _n / Residual Current Circuit Breaker	Entry	Screw Size	Order No.
2 sockets with earthing contact			—	25A/30mA/2p.	M 20		2318073
3 sockets with earthing contact			—	25A/30mA/2p.	M 20		2318072
3 sockets with earthing contact			—	40A/30mA/4p.	M 20		2318070
4 sockets with earthing contact			4 B-Autom. 1p.	—	M 25		2348030



1 CEE 400V 16A 5p. 2 sockets with earthing contact			— 2 B-Autom. 1p.	40A/30mA/4p.	M 32		2358150
1 CEE 400V 32A 5p. 2 sockets with earthing contact			— 2 B-Autom. 1p.	40A/30mA/4p.	M 32		2358314



1 CEE 400V 16A 5p.			—	40A/30mA/4p.	M 20		2318160
1 CEE 400V 32A 5p.			—	40A/30mA/4p.	M 25		2318320



1 screw sized M 25			—	40A/30mA/4p.	M 25		2318830
1 screw sized M 32			—	63A/30mA/4p.	M 32		2318840

– other cable lengths and further models on request / subject to modification and errors –